### Suzanne Steab - August 2011 Inspection Report

From:

Karl Houskeeper

To:

knicholes@altoncoal.com

Date:

9/15/2011 2:05 PM

Subject:

August 2011 Inspection Report

CC:

ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov

Attachments: Coal Hollow August 2011.pdf

Kirk,

Attached is the August 2011 inspection report for Coal Hollow.

Thanks, Karl



## State of Utah

#### **DEPARTMENT OF NATURAL RESOURCES**

MICHAEL R. STYLER

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Representatives Present During the Inspection:							
Company	Kirk Nicholes						
OGM	Karl Houskeeper						

# **Inspection Report**

Permit Number:	C0250005		
Inspection Type:	PARTIAL		
Inspection Date:	Tuesday, August 02, 2011		
Start Date/Time:	8/2/2011 1:30:00 PM		
End Date/Time:	8/2/2011 3:30:00 PM		
Last Inspection:	Thursday, July 14, 2011		

Inspector: Karl Houskeeper,

Weather: Partly Cloudy, Temp 83 Deg. F.

**Types of Operations** Underground **⊻** Surface Loadout Processing Reprocessing

InspectionID Report Number: 2816

Accepted by: jhelfric 8/8/2011

Permitee: ALTON COAL DEVELOPMENT LLC Operator: ALTON COAL DEVELOPMENT LLC

Site: COAL HOLLOW

Address: 463 North 100 West, Suite 1, CEDAR CITY UT 84720

County: KANE

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages	Mineral Ownership		
635.64 Total Permitted	✓ Federal		
435.00 Total Disturbed	☐ State		
Phase I	County		
Phase II	<b>✓</b> Fee		
Phase III	Other		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

inspector's Signature:

Karl Houskeeper,

Inspector ID Number: 49

Tuesday, Augu

Permit Number: C0250005 Inspection Type: PARTIAL

Inspection Date: Tuesday, August 02, 2011

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  For PARTIAL inspections check only the elements evaluated.
  Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
  Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
  Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale		:	1	
2.	Signs and Markers	<b>∀</b>	:-1	~	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	¥		<b>Y</b>	:::
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	y		¥.	
4.c	Hydrologic Balance: Other Sediment Control Measures	)	T T		
4.d	Hydrologic Balance: Water Monitoring			[]	: ]
4.8	Hydrologic Balance: Effluent Limitations	II.)			
5.	Explosives	<b>y</b>		V	, , , , , , , , , , , , , , , , , , ,
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments			1.1	
8.	Noncoal Waste		C)	<b>E</b>	
9.	Protection of Fish, Wildlife and Related Environmental Issues	-			: 1
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation	1777 5	[ ]		:]
12.	Backfilling And Grading		111		/A.M.
13.	Revegetation	: 1			
14.	Subsidence Control	2	[]		100 mg
15.	Cessation of Operations		;		[
16.a	Roads: Construction, Maintenance, Surfacing		1.1		1.1
16.b	Roads: Drainage Controls		arm reg	1007.01.00	
17.	Other Transportation Facilities	1 1	America a	[1]	
18.	Support Facilities, Utility Installations	( )	l		
19.	AVS Check		( )	]	: ""
20.	Air Quality Permit				
21.	Bonding and Insurance			1	
22.	Other		[]		[]

Permit Number: C0250005 Inspection Type: PARTIAL

Inspection Date: Tuesday, August 02, 2011

Page 3 of 3

#### 2. Signs and Markers

Mine identification signs are in place at the points of public access into the permit area. The signs contain the required information.

#### 4.a Hydrologic Balance: Diversions

Top of culvert that leads into sediment pond #1B is smashed. The operator plans on replacing this culvert when installing other needed culverts at the mine site. The operator has submitted a Drainage Control Amendment to the Division which was just returned with deficiencies. Once this amendment is approved the smashed culvert will be replaced. The culvert is still functional as efforts have been made to lift the smashed portion.

### 4.b Hydrologic Balance: Sediment Ponds and Impoundments

The open channel spill way from sediment pond #3 has been re-worked into a concave design with the rip rap. Larger rip rap has been placed to the outside and gradations of smaller rip rap toward the center. Water is still present inside of pond #3, but has diminished substantially since the previous inspection.

#### 5. Explosives

Information is being gathered for pre-blast survey of structures around the mine site to keep on file in case blasting is ever needed.